

14198
Lancaster Tank & Truck Wash
Ken Banzhof
798 Flory Mill Rd
Lancaster , PA 17601

Project Lancaster Tank Wash
Information :

Report Date : 08/20/2020
Received : 08/19/2020

Report Number : **20-232-0008**

Water Analysis Report

Lab No : **97260**
Sample ID : **water**

Matrix: **Aqueous**
Sampled: **8/19/2020 11:37**

Test	Results	Units	MQL	DF	Date / Time Analyzed	By	Analytical Method
Total Coliform	<1	MPN/100mL	1	1	08/19/20 12:58	RLF	9223B-2004
E-coli	<1	MPN/100mL	1	1	08/19/20 12:58	RLF	9223B-2004

**Qualifiers/
Definitions**

DF Dilution Factor
MQL Method Quantitation Limit

L Limit Exceeded