

14198
Lancaster Tank & Truck Wash
Ken Banzhof
798 Flory Mill Rd
Lancaster , PA 17601

Project Lancaster Tank Wash
Information :

Report Date : 8/8/2018

Report Number : **18-219-0004**

Water Analysis Report

Received : 8/7/2018

Lab No : **99291**
Sample ID : **water**

Matrix: **Aqueous**
Sampled: **8/7/2018 10:44**

Test	Results	Units	MQL	DF	Date / Time Analyzed	By	Analytical Method
Total Coliform	<1	MPN/100mL	1	1	08/08/18 14:52	RLF	9223B-2004
E-coli	<1	MPN/100mL	1	1	08/08/18 14:52	RLF	9223B-2004

**Qualifiers/
Definitions**

DF

Dilution Factor

MQL

Method Quantitation Limit